July 6, 2001 Atty Ref: OPS Case 537

BRIEF DESCRIPTION OF DRAWINGS

Figs. 1(a), 1(b), 1(c), 1(d), 1(e), 1(f) and 1(g) are views for showing the process of a first manufacturing method.

Fig. 2 is a flow sheet for explaining a second manufacturing method.

Figs. 3(a), 3(b), 3(c) and 3(d) are views for showing the first half of the process of the second manufacturing method.

Figs. 4(a), 4(b) and 4(c) are views for showing the second half of the process of the second manufacturing method.

A

DOBOZEB"OZOBOT